

## Damage Status from Great Higashinohon Earthquake Report No. 3

We wish to express our condolences to all those affected by the Tohoku-Kanto Earthquake.

Updated damage and recovery reports for facilities operated by Shindengen Group companies are as follows.

- 1 Akita Shindengen Co., Ltd. in Ohura, Yurihonjo, Akita
  - A) At the Ohura (downstream process) factory: Inspection of production equipment is largely complete, and despite continued restrictions to the electrical power supply, almost all products are once again under production.
  - B) At the Asuka (upstream process) factory: Inspection of production equipment is largely complete, and despite continued restrictions to the electrical power supply, production is scheduled to begin this week on a sequential basis.
  
- 2 Higashine Shindengen Co., Ltd. in Higashine, Yamagata
  - A) Inspection of production equipment is largely complete, and despite continued restrictions to the electrical power supply, production is scheduled to begin this week on a sequential basis.

We anticipate that, because of rolling blackouts implemented by Tohoku Electric Power Company and difficulties in obtaining gas and other fuels due to the breakdown of distribution networks, a significant period of time will be required to return to normal production levels.

In addition, the following facilities in the Kanto region are operating at close to normal production levels despite being affected by rolling blackouts implemented by Tokyo Electric Power Company and difficulties in obtaining materials.

Okabe Shindengen Co., Ltd in Fukaya, Saitama

Power modules product

Shindengen Three E Co., Ltd in Ino, Saitama

Power system products

As of 15:00 p.m. March 22, 2011

Shindengen Electric Manufacturing Co., Ltd.

Public Relations & IR staff, Planning Section, Corporate Planning Department