

Damage Status from Great Higashinihon Earthquake Report No.5

We would like to extend our deepest sympathy to all victims of the Great Tohoku Kanto Earthquake.

The table below shows the latest report on damage and recovery from Shindengen Group companies in the northern area.

[Underlined parts : changed from previous report]

| Company | Plant/Process | Location | Building | Production Line/Equipment | | | Power | Logistics |
|----------------------|---------------------------------|--------------------------|-----------|---------------------------|--|-----------------------------------|----------------------|-------------------|
| | | | | Check | Status | Production | | |
| Akita Shindengen | Asuka plant (front-end process) | Yurihonjyo City, Akita | No damage | Complete | <u>No problem</u> | <u>Ongoing</u> | Supplied but limited | <u>No problem</u> |
| | Ooura plant (finishing) | | | Complete | No problem | Ongoing | | |
| Higashine Shindengen | Front-end process | Higashine City, Yamagata | | Mostly complete | No major problem Some adjustment ongoing | Ongoing (Capacity reduced by 20%) | Supplied | |
| | Finishing | | | Complete | No problem | Ongoing | | |

Please note that the information above is as of March 24, and our production capacity might be affected by a limited supply of fuel, gas, and rolling blackouts.

We are happy to inform all of our customers that there was no serious damage that affects the production and delivery of our products.

As of 4:00 p.m. March 30, 2011

Shindengen Electric Manufacturing Co., Ltd.

Public Relations & IR staff, Planning Section, Corporate Planning Department