

## Damage from the Afterquake at Midnight on April 7th No. 2

We would like to report the following information concerning damage incurred at our company due to the afterquake which occurred at 23:32 on April 7th, Thursday offshore of Miyagi, and the progress of recovery.

1. Akita Shindengen Co., Ltd. (114-2, Aza Kamiyachi, Ooura, Yurihonjyo City, Akita)
  - (1) Ooura plant (finishing ): facility check has been completed and the production has been resumed
  - (2) Asuka plant (front-end process): facility check has been completed and the production has been resumed
  
2. Higashine Shindengen Co., Ltd. (5600-1, Kou, Ooaza Higashine, Higashine city, Yamagata)
  - (1) Currently performing a facility check (planned to be completed today).  
Production is to resume on April 12th (Tuesday).

As of 11:00 a.m. April 11th, 2011  
Shindengen Electric Manufacturing Co., Ltd.  
Public Relations & IR staff, Planning Section, Corporate Planning Department