

## Damage Status from Great Higashinihon Earthquake Report No.6

The table below shows the latest report on damage and recovery from Shindengen Group companies in the northern area.

Company	Plant/Process	Location	Building	Production Line/Equipment			Power	Logistics
				Check	Status	Production		
Akita Shindengen	Asuka plant (front-end process)	Yurihonjyo City, Akita	No damage	Complete	No problem	Ongoing	Supplied but limited	No problem
	Ooura plant (finishing)			Complete	No problem	Ongoing		
Higashine Shindengen	Front-end process	Higashine City, Yamagata		Mostly complete	No major problem Some adjustment ongoing	Ongoing (Capacity reduced by 20%)	Supplied	
	Finishing			Complete	No problem	Ongoing		

As of 11:00 A.m. April 12, 2011

Shindengen Electric Manufacturing Co., Ltd.

Public Relations & IR staff, Planning Section, Corporate Planning Department