

Report on the Impact of the Current Floods in Thailand (6th Report)

The following is the latest information regarding the Shindengen Group production sites affected by the floods in Thailand.

(1) SHINDENGEN (THAILAND) CO., LTD.

Location: 60/58 MOO 19 SOI NAVA NAKORN 13 KLONGNUENG,
KLONGLUANG, PATHUMTHANI 12120, THAILAND

Main Business: Manufacture and sale of car electronics products.

Manufacture of semiconductor products.

Water is drained from the plant buildings and rest of the premises. Currently our staff is in the process of performing cleaning and facility checks.

While we wait for the completion of our alternate production sites in Thailand, the products are being temporarily manufactured by our Group companies in Japan, China, Indonesia, Vietnam and India, and we are taking every possible measure to ensure enough parts are available for stable supply.

* We are happy to report that Lumphun Shindengen Co., Ltd., located in the northern industrial complex of Lumphun Province, which was adjusting the volume of semiconductor production due to reduced supply of raw materials, has resumed its regular production.

We will report any change in the situation, as and when further information becomes available.

As of 12:00 p.m. January 19, 2012

Shindengen Electric Manufacturing Co., Ltd.

Public Relations & IR staff, Planning Section, Corporate Planning Department